
Bentley & VW Phaeton(2010~2018) VW RNS510 Radio WIRING DIAGRAM---LDS-BLY80-CP



PIN8 0FF/0N After market rear view camera/Original rear view camera

Reset Dip Switch LED



 After disassembling the panel, cover and the screws of the original engine, install the copper column in the position specified in the figure. 2).Insert the 50PIN and on the switching board with the original headunit, fix the switching board with the screws removed from the original headunit, and then insert the LVDS line and pay attention to the outlet position. The movement and upper cover are then installed, as shown above.

 Insert the three lines of the original headunit's panel (50PIN FPC/12PIN/SD card cable). Then restore the panel of the headunit.

Remark: For the Bently with orginal DAB function, you can only use our switch button key to switch the CarPlay interface.